

Knot Filling


Newly developed Polyamide glue is very effective and easy to use for repair of edges and corners. Knot holes are nearly invisibly filled. The Polyamide glue is sold in 10 various colours making repairs of almost any type of wood possible.



Hotmelt Gun e.g. BeA 285



Knot hole



New repaired knot hole

After a relatively short cooling period you can easily remove the surplus glue with a sharp cutting alloy or chisel. The knot filling glue hardens slowly making it easy to cut. This makes the repair look nice and fit with the wood.



Cutting surfaces



Cutting edges

When the surplus glue has been removed and the surface is clean and smooth, you can give the wood a finishing treatment of cellulose paint, lye or paint.



Tools for repair



Choice of colours

Joh. Friedrich Behrens AG
BeA Deutschland Befestigungstechnik

Bogenstrasse 43 – 45
D – 22926 Ahrensburg

Tel. 041 02 – 78 – 0
Fax 041 02 – 78 – 270

info@bea-group.com
www.bea-group.com